



Phase Diagrams of Fe-P and Fe-N

Illustration

Here are the phase diagrams for iron and nitrogen (Fe - N), and [iron and phosphorous](#) (Fe - P).



More detailed versions can be found in the [backbone part](#).